


Sticklers™ CleanStixx™ - 1.2 mm EB Connector Cleaning Sticks


PART NUMBER: MCC-EB12



Video:
How to Use CleanStixx™
@ SticklersCleaners.com




MIL 29504/5



SFP+ Transceiver Module

Product Features:

- Saddle shaped cleaning tip conforms to lens and ferrule end face for full contact
- Prevents triboelectric and electrostatic induction when used with the Sticklers Fiber Optic Splice & Connector Cleaner precision cleaning fluid
- 5 Sealed Sleeves with 10 sticks per sleeve to maintain cleanliness
- Lot number listed on each sleeve for quality





For best results, use with:
Sticklers™ Fiber Optic Splice & Connector Cleaner
Part Number: MCC-POC03M



CleanStixx™ Connector Cleaning Sticks Deliver Fast & Consistent Results

The fibers spread apart and grip particulate. Capillary action wicks liquids from the surface.

On the head of each CleanStixx™, fibers flex to easily conform to the end-face.



RECOMMENDED USES:

CONNECTOR SYSTEMS:

- Ø1.2mm Expanded Beam MIL 29504/5 Socket Termini
- ARINC 801 Socket Termini
- SFP+ optical transceiver modules
- ODC/RDC/AARC style FTTA connectors
- In Bulk Head LC and MU connectors

TYPICAL APPLICATIONS:

- Commercial Aviation
- Enterprise Networks
- Military Aviation
- Equipment Production
- Fiber To The Antenna
- Installation Kits

When You Need Perfectly Clean Splices & Connectors™



SticklersCleaners.com

 Follow Us!

MicroCare, LLC

595 John Downey Drive
New Britain, CT 06051 USA
Tel: +1 860 827 0626
Toll Free: 1 800 638 0125
Email: TechSupport@MicroCare.com

MicroCare U.K. Ltd

Unit 4, Whitehall Court
Leeds
LS12 5SN UK
Tel: +44 (0) 113 3609019
Email: MCCEurope@MicroCare.com

MicroCare Asia Pte Ltd

102E, Pasir Panjang Road
Citilink, #05-06
Singapore 118529
Tel: +65 6271 0182
Email: TechSupport@MicroCare.sg



For more information and to download SDS visit our website:
SticklersCleaners.com